Final

Close-Out Report

Site 16 - Chemical Fire, Building X-136

Naval Station Norfolk Norfolk, Virginia



Prepared for

Department of the Navy Atlantic Division Naval Facilities Engineering Command

> Under the LANTDIV CLEAN II Program Contract N62470-95-D-6007 Contract Task Order 0075 May 2002

> > Prepared by



Virginia Beach, Virginia

Final

Close-Out Report Site 16 - Chemical Fire, Building X-136

Naval Station Norfolk Norfolk, Virginia

In accordance with the Federal Facilities Agreement for the Naval Station Norfolk, signed February 1999, a Closeout Report was completed for Site 16 - Chemical Fire, Building X-136. The site Project Managers and members of the Naval Station Norfolk Tier I Partnership determined that no further action is required and the land use will be unrestricted at the site. This evaluation was based on consideration of field sampling data for soil and groundwater, risk screening, and professional judgement. In the event contamination posing an unacceptable risk to human health or the environment is discovered after execution of this site closeout report, the Partnership agrees to remediate the contamination if deemed necessary.

1/an/are	17 May 200
Mary Cooke	Date

Project Manager EPA Region 3

Project Manager

Naval Facilities Engineering Command

John/Tomik

Project Manager CH2M HILL

Devlin Harris

Project Manager

Virginia DEQ

Randy Sawyer

IR Program Coordinator Navy PWC, Norfolk

Table of Contents

Table of Contents	ii:
1.0 Introduction	
Site Description	
Summary of Previous Investigations	
2.0 Field Activities	
3.0 Risk Characterization	
Subsurface Soil	
Groundwater	
Human Health Risk Assessment	
Ecological Risk Assessment	
4.0 Conclusions and Recommendations	
5.0 References	
Figures	
Figure 1-1 Location Map	1-3
Figure 1-2 Site 16 Area Map	
Figure 2-1 Sampling Locations Map	
Figure 3-1 Exceedances Map	
Tables	
Table 3-1 Subsurface Soil Exceedances, Baker RRR Study	3-3
Table 3-2 Groundwater Exceedances, Baker RRR Study	
Table 3-3 Groundwater Exceedances, CH2M HILL Site Investigation Study	3-5
Table 3-4 Groundwater Exceedances, CH2M HILL Additional Sampling	3-6

2.0 Field Activities

This section presents information regarding the sampling activities conducted at Site 16. Details on the number of samples collected, collection methods, sampling locations, and sample analysis are provided below.

During the 1996 Phase I RRR study, a total of seven samples (4 subsurface soil and 3 grab groundwater) were collected for analysis. Sample locations and selection of analyte parameters were based on a site reconnaissance and site history review performed prior to the field sampling event. See Figure 2-1 for locations where samples were collected. The samples were analyzed for Volatile Organic Compounds (VOCs), Semi-Volatile Organic Compounds (SVOCs), Target Analyte List (TAL) Metals and Cyanide, Target Compound List (TCL) Pesticide and Polychlorinated Biphenyls (PCBs).

During the 2001 Supplemental Investigation, three monitoring wells were installed and subsequently groundwater samples were collected. The monitoring well locations (See Figure 2-1) were selected based on a review of the existing analytical data and presented in a work plan (CH2M HIIL, 2001) approved by the Naval Station Norfolk Tier I Partnering Team. The monitoring wells were installed at depths ranging from 15 to 16 feet below ground surface (bgs) based upon the depth to first encountered water. The wells were constructed of 2-inch diameter PVC well casings with 10-foot well screens. The monitoring wells were installed using a hollow stem auger (HSA) drill rig with 4¼" inner diameter auger stems. Groundwater samples were analyzed for VOCs.

The groundwater sample collected in August of 2001 was collected from the existing monitoring well, MW01S (See Figure 2-1 for location). The sample was analyzed for VOCs.

CLOSEOUT REPORT SITE 16 2-1

3.0 Risk Characterization

The following section presents the interpretation of the analytical data from the 1996 Phase I RRR study, 2001 Supplemental Investigation, and August 2001 groundwater sample. The discussion includes the identification of screening/regulatory criteria exceedances, as well as exceedances of upgradient, background and offsite concentrations. Concentrations of detected chemicals were compared to the following current USEPA screening and regulatory screening criteria for each sample matrix: USEPA Region III residential and industrial risk-based concentrations (RBCs) for soil, and USEPA Region III tap water RBCs, and primary drinking water Maximum Contaminant Levels (MCLs) for groundwater.

Subsurface Soil

The analytical results from the 1996 Phase I RRR Study (Baker 1996) show that there were few exceedances detected for the analytes above residential or industrial soil RBCs. No VOCs exceeded the screening criteria in soil. One semi-volatile organic compound, Benzo(a)pyrene, exceeded its residential and industrial RBC for soil. Benzo(b)fluoranthene exceeded its residential RBC for soil, but not the corresponding industrial RBC. Pesticides and PCBs were not detected at levels that exceeded any corresponding RBC values. Arsenic, ubiquitous in this geographic region, was the only inorganic compound detected above its industrial soil ingestion RBC or above its residential soil ingestion RBC. A comparison of the detected compounds with the residential soil RBCs is given in Table 3-1. Exceedance information is also presented in Figure 3-1.

The Soil Background Investigation of Naval Station Norfolk (CH2M HILL, 2000) shows that the background soil arsenic concentrations are typically elevated at the base with ranges of 12.7 mg/L to 28.6 mg/L. Therefore, it is likely that the arsenic concentrations detected at the site are due to background conditions and are not site-related.

Groundwater

The groundwater results from the 1996 Phase I RRR Study (Baker 1996) showed exceedances of the tapwater RBCs for the following organic compounds: 1,2 dichloroethene (1,2-DCE), benzene, trichloroethene (TCE), and naphthalene. The maximum concentrations for 1,2-DCE and TCE also exceeded their respective MCLs. The inorganic analysis showed that there was a RBC and MCL exceedance for arsenic as well as an RBC exceedance for iron. In addition, the lead concentration slightly exceeded the National Primary Drinking Water Action Level of 15 ug/L at one location. However, the arsenic concentrations are typically elevated in this region and inorganics are not expected to be site related contaminants. The elevated levels of inorganics may be attributable to background. These results are presented in Table 3-2. The 1996 groundwater samples were collected using a Geoprobe, which is allowed by EPA and DEQ to be used only as a qualitative tool for the assessment of groundwater quality data. As a result, in 2001 three groundwater monitoring wells were installed at Site 16 to provide more quantitative and updated groundwater data for the site.

CLOSEOUT REPORT SITE 16 3-1

The groundwater results from the 2001 Investigation Report (CH2M HILL 2001) show that there was one MCL exceedance at monitoring well MW01S. The exceedance was for vinyl chloride (VC). In addition, TCE and VC exceeded their respective tap water RBCs. Exceedance information is presented in Table 3-3. In Figure 3-1, data from the August 2001 sampling event replaced the sampling from the Investigation Report for monitoring well MW01S.

In August of 2001, MW01S was resampled for VOCs. No VOCs, including VC, were detected at levels above their MCLs. Exceedance Information is presented in Table 3-4 and Figure 3-1.

Human Health Risk Assessment

A qualitative assessment for human health indicates the site is not expected to pose an unacceptable risk to human health due to the low level of contamination and limited exposure pathways.

Ecological Risk Assessment

A qualitative assessment for ecological risk indicates the site is not expected to pose an unacceptable ecological risk due to the low level of contamination and limited pathways by which receptors may be exposed. The site is in an industrialized area where the majority of site soils have been covered with pavement materials. There is minimal potential for exposure through incidental ingestion of contaminated surface soil or direct exposure. The migration of contamination to sediments or surface water through groundwater or runoff would be very slow and is not likely to occur.

CLOSEOUT REPORT SITE 16

		Table 3-1					
		e Soil Exceedance	206				
		er RRR Study	<i>7</i> .5				
		Station Norfolk					
Station ID	RBC-Soil	Otation Honork		IOF			
Sample ID	Residential	NB05					
Chemical Name		NB05D1	NB05D2	NB05D3	NB05D4		
Citerrical Name	- -			<u> </u>	ļ		
Sami valetile Omania Compayada (IIC/I/C)							
Semi-volatile Organic Compounds (UG/KG) Acenaphthene	4700000	NA NA	40 J	NA NA	NA NA		
Acenaphthylene	4700000	NA NA	68 J	NA NA	NA NA		
Anthracene	23,000,000	NA NA	660	NA NA	NA NA		
Benzo(a)anthracene	870	NA NA	790	NA NA	NA NA		
Benzo(a)pyrene	87	NA NA	900	NA NA	NA NA		
Benzo(b)fluoranthene	870	NA NA	71400	NA NA	NA NA		
Benzo(g,h,i)perylene	2,300,000	NA NA	1900 J	NA NA	NA NA		
Benzo(k)fluoranthene	8,700	NA NA	1100	NA NA	NA NA		
Carbozole	32,000	NA NA	97 J	NA NA	NA NA		
Chrysene	87,000	NA NA	1200	NA NA	NA NA		
Dibutyl phthalate		61 BJ	NA	NA NA	NA NA		
Fluoranthene	3,100,000	NA NA	1700	NA NA	NA NA		
Fluorene	3,100,000	NA NA	74 J	NA NA	NA NA		
Indeno(1,2,3-cd)pyrene	870	NA NA	250 J	NA NA	NA NA		
Phenanthrene	2,300,000	NA	330 J	NA NA	NA NA		
Pyrene	2,300,000	NA NA	1200	NA	NA NA		
bis(2-Ethylhexyl)phthalate	46,000	NA.	36 J	NA NA	NA NA		
Pesticide/Polychiorinated Biphenyls (UG/KG)							
4,4'-DDT	1,900	NA NA	31	NA	NA:		
Total Metals (MG/KG)	. .	of the same of the		AND THE RESIDENCE OF THE PROPERTY OF THE PROPE			
Aluminum	78,000	8,750	NA NA	NA	NA		
Arsenic	0.43	NA	NA NA	NA	2004007.9		
Barium	5,500	NA	44.6	NA	NA		
Caldum		NA	NA NA	110,000	NA NA		
Chromium	230	NA	18,2	NA NA	NA		
Copper	3,100	NA NA	14.1	NA NA	NA NA		
Iron	47,000	NA NA	NA NA	NA NA	16,900		
Lead	400	NA NA	93.5	NA NA	NA		
Magnesium	1	NA NA	NA NA	NA NA	3,560		
Manganese	1,600	236	NA NA	NA NA	NA NA		
Mercury	23	NA	0.25	NA	NA NA		
Nickel	1,600	NA	NA NA	NA NA	10		
Potassium	1	NA	NA NA	NA NA	1,520		
Sodium	11	NA.	NA NA	963.0	NA NA		
Vanadium	550	22.2	NA NA	NA NA	NA NA		
Zinc	23,000	NA NA	126	NA NA	NA NA		

Exceeds one or more criteria

NA: Not Analyzed

B-Analyte Not detected above associated blank J- Reported value is estimated

Table 3-3 **Groundwater Exceedances** CH2M HILL Site Investigation Report Naval Station Norfolk

Naval Station Norfolk							
Station ID	RBC- MCL-		NBS16-M	IW01S	NBS16-MW02S	NBS16-MW03S	
Sample ID	Tap	Ground	NBS16-MW01S-P-R01 NBS16-MW01S-R01		NBS16-MW02S-R01	NBS16-MW03S-R01	
Sample Date]	water	06/28/01	06/28/01	06/28/01	06/28/01	
Chemical Name							
Volatile Organic Compounds (UG/L)							
Acetone	610		2.4 B	10 UJ	40 J	2 B	
Toluene	750	1,000	10 U	10 U	. 1.2 J	10 U	
Trichloroethene	1.6	5	29 J	10.02900	10 U	10 U	
Vinyl chloride	0.015	2	2. 42.5 U	28 (8	10 U	10 U	
Xylene, total	12,000	10,000		10 U	1.3 J	10 U	
cis-1,2-Dichloroethene	61	70	29	26	10 U	10 U	
trans-1,2-Dichloroethene	120	100	1.1 J	10 U	10 U	10 U	

NA - Not analyzed

B- Analyte not detected above associated blank
J - Reported value is estimated


U - Analyte not detected

Table 3-4 Groundwater Exceedances CH2M HILL Additional Sampling Naval Station Norfolk							
Station ID	RBC-	MCL-	NBS16-MW01S				
Sample ID	Tap	Groundwater	NBS16-MW01S-P-R02	NBS16-MW01S-R02			
Sample Date		O. Gandwater	08/24/01	08/24/01			
Chemical Name							
Volatile Organic Compounds (UG/L)							
Trichloroethene	1.6	5	95	350			
Vinyl chloride	0.015	2	76. (E3.2) (H2)	WATER SECTION			
cis-1,2-Dichloroethene	61	70	28	27			
trans-1,2-Dichloroethene	120	100	1 J	10 U			

Exceeds one or more criteria
NA - Not analyzed

B- Analyte not detected above associated blank

J - Reported value is estimated U - Analyte not detected



4.0 Conclusions and Recommendations

The following conclusions are based upon a complete review of all available analytical data collected during the 1996 Phase I RRR study, 2001 Supplemental Investigation, and the additional 2001 sampling event. The soil analytical data was compared to background data and the current USEPA risk-based residential and industrial concentrations (RBCs) for soil. The groundwater analytical data was compared to the tap water RBCs and the primary drinking water Maximum Contaminant Levels (MCLs).

- The soil analytical results show that there were no VOCs exceeded the screening criteria in soil. One semi-volatile organic compound, Benzo(a)pyrene, exceeded its residential and industrial RBC for soil. Benzo(b)fluoranthene exceeded its residential RBC for soil, but not the corresponding industrial RBC. Pesticides and PCBs were not detected at levels that exceeded any corresponding RBC values. Arsenic was the only inorganic compound detected above its industrial soil ingestion RBC or above its residential soil ingestion RBC. The Soil Background Investigation of Naval Station Norfolk (CH2M HILL, 2000) shows that the background soil arsenic concentrations are typically elevated at the base with ranges of 12.7 mg/L to 28.6 mg/L. Therefore, it is likely that the arsenic concentrations detected at the site are due to background conditions and are not site-related.
- The most recent groundwater results indicate that no compounds were detected above their respective MCLs at the site. Only two compounds, VC and TCE, exceeded tapwater RBCs.

A qualitative assessment for human health indicates the site is not expected to pose an unacceptable risk to human health due to the low level of contamination and limited exposure pathways.

A qualitative assessment for ecological risk indicates the site is not expected to pose an unacceptable ecological risk due to the low level of contamination and limited pathways by which receptors may be exposed. The site is in an industrialized area where the majority of site soils have been covered with pavement materials. There is minimal potential for exposure through incidental ingestion of contaminated surface soil or direct exposure. The migration of contamination to sediments or surface water through groundwater or runoff would be very slow and is not likely to occur.

Based on this evaluation, no further action is recommended for this site.

CLOSEOUT REPORT SITE 16 4-1

5.0 References

Baker Environmental Inc., January 1996. Final Relative Risk Ranking System Data Collection Sampling and Analysis Report, Naval Base, Norfolk, Virginia.

CH2MHILL, September 2000. Soil Background Investigation Report, Naval Station Norfolk, Norfolk, Virginia.

CH2M HILL, September 2001. Site Investigation Report for Sites 10, 16, and 18 at Naval Station Norfolk.

Environmental Science and Engineering, Inc., February 1983. Initial Assessment Study, Sewells Point Naval Complex, Norfolk, Virginia.

CH2M HILL, January 2002. Presentation to the Tier I Partnering Team: Results of the Additional Sampling at Site 16.

CLOSEOUT REPORT SITE 16 5-1